



PUBLIC WORKS DEPARTMENT (B & R), HARYANA



OFFICE OF THE SUB DIVISIONAL ENGINEER
PROVINCIAL SUB DIVISION No.4, GURUGRAM
Email ID: sdepsd4@gmail.com

No. 499

Dated 27/2/2020

BUILDING SAFETY CERTIFICATE

Considering the request of Prinicipal, Maharishi Vidya Mandir Sr. Sec., School Village Chandu, P.O. Garhi Harsaru, Distt Gurugram (Haryana) the building was inspected by the undersigned alongwith with Manoj Kumar, JE on dated 25.10.2019 at that time some repair work are necessary in the Building. The site was inspected again on 27.02.2020 & found that necessary repair has been done by the concerned authority. It was found from visual inspection that the present condition of the buiding is satisfactory and the building seems to be safe for the purpose of running the School. So, the certificate regarding the building safety is hereby issued which will be valid for one year from the date its issuance i.e. 27.02.2020.

Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram.

Endst No.


Dated

Copy of above is forwarded to the following for information and necessary action:-

1. The Prinicipal, Maharishi Vidya Mandir Sr. Sec., School Village Chandu, P.O. Garhi Harsaru, Distt Gurugram (Haryana)
2. Executive Engineer, Provincial Division No.II, PWD B&R Br., Gurugram for information w.r.t. his office endst no.6165 dated 13.06.2019.

DA/Nil


Principal
Maharishi Vidya Mandir
Sr. Sec. School
Chandu, Gurugram (Hr.)


Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram